

300 Cloverleaf Road, York, PA 17406 www.aaronenterprises.com 717-854-2641

Project:	New Jersey Transit Reline	
Location:	Cherry Hill, NJ	

Project Details:

A large diameter corrugated metal pipe was failing under NJ Transit rails near Cherry Hill New Jersey. The 135 LF crossing was a candidate for rehabilitation. NJ Transit maintenance crews removed debris from within the host and performed the liner pipe installation. AEI installed structural blocking within the liner and pumped a 35 PCF lightweight cellular grout in the annular space between the liner and the host.

Final Product: 135LF of 84" diameter Contech DuroMaxx Liner within a 96" Diameter CMP

Project Profile Grouting

Completion Date October 2019

Installation Methods:

Pipe Rehabilitation Grouting

Markets Served:

Heavy Civil Construction Railway Transportation Storm Water



<u>Owner:</u>	Engineer:	Contractor:
NJ Transit	DL VEWS	NJ Transit

For More Information:

Robert L. McDowell, PE - Project Manager - (717) 854-2641 ext. 230 Reference Job # 1925558

